



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

September 28, 2006

Supervisor 10027

Mine Name: North Slope

Operator Name: Tony Peck

(Interstate Brick Company)

Inspector(s): Lynn Kunzler, DOGM

Other Participants: John Hewitt

Permit number: M0490028

Inspection Date: August 22, 2006

Time: 12:30 pm

Mine Status: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Operator had requested an inspection to release this site.

Inspection Summary:

This site was permitted in 1996. it is located west of the Allred permit area. There has been no reported activity for 1997-2005. The 10- year window of continued suspension before reclamation is required is fast approaching.

Less than 1 acre has been disturbed at this site, which occurred almost 10 years ago. This disturbance has not been reclaimed. Mr. Hewitt indicated that he would have this area reclaimed this fall.

Conclusions and Recommendations:

This file cannot be closed at this time. The operator will need to pay the annual permit fee of \$150.00. If reclamation work is not completed this fall, the operator will need to provide a reclamation surety in the amount of \$5,400.00. Since it has been almost 10 years since this site was active, the operator should also be notified that if reclamation is not completed this fall he will need to appear before the Board to justify why he could should not reclaim the site immediately.

Inspector's Signature

LK:pb

O:\M049-Utah\S0490028-NorthSlope\inspections\insp-08222006.doc

Date: September 28, 2006